## **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: <u>SF/ALA</u> Rte: <u>80</u> PM: <u>13.2/13.9</u>

File #: 69.12

## **DAILY PROJECT JOURNAL**

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000692 **Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Dated: 21-Feb-2008

**Location:** Changxing Island, Shanghai, PRC

Submittals(New / Total): CWR's: / HSR's: / NCR's: /			
Item	Title		Detail
1	Meetings attended		0730-Attended the METS Weekly teleconference.
2	Other important observations		At 0900 I went on a shop floor walkthrough with Ryan Smith and Mazen
			Wahbeh and observed following:
			77m- Visually selected locations for macroetch selection for tower acceptance.
			89m-Welding on the diagonal stiffeners between skin C and D. Drilling on face D.
			114m-Scaffolding erected and sections in the upright positions. Exterior
			splice plates are in position and internal connection plates are present.
3	Key conversations		Talked to Kevin Carpenter and gave him the list of weld joint numbers on
			the 77m mockup which we need NDT reports on. Mr. Carpenter told me
			that he would work on compiling them.
Inspected By: Ishibashi,Josh			Quality Assurance Inspector
Reviewed By: Wahbeh, Mazen			QA Reviewer